

CASE STUDY – Rendering Facility

Issue: A large animal rendering facility was under threat of closure by the municipality for strong and (very) unpleasant odour emissions and pest detection offences probably also due to biofilm build up. The facility was routinely cleaned and was spending £50K+ a month on chemicals to mask the odours but was still unable to resolve the problem.

Solution: Odorox® technology (MVP 14 and MVP48 units) permanently installed at strategic points in the facility.

Outcome: The installation quickly resolved the odour and pest problems and also saved the money spent on chemicals. Plus reduced water consumption by 10,000 gallons a month and reversed biofilm collection over time. Then site is now considered a ‘clean model’ rendering facility within the industry.

